







DELAY -> 7SEC 5 V 34 OPEN (SPRAY RICE) DELAY -> 40 SEC S V 34 CLOSE CLOSE SV 45 TURN ON HEATERS LOW DELAY -> 50 SEC TURN OFF HEATERS TURN OFF INDICATOR 9 TURN ON IND . 10 END





